

SDMS US EPA Region V

Imagery Insert Form

Document ID:

297063

Some images in this document may be illegible or unavailable in SDMS.

Please see reason(s) indicated below:

EPA Region 5 Records Ctr.



297063

X

Illegible due to bad source documents. Image(s) in SDMS is equivalent to hard copy.

Specify Type of Document(s) / Comments:

TEXT IN THE MIDDLE OF PAGE

Includes ____ COLOR or ____ RESOLUTION variations.

Unless otherwise noted, these pages are available in monochrome. The source document page(s) is more legible than the images. The original document is available for viewing at the Superfund Records Center.

Specify Type of Document(s) / Comments:

Confidential Business Information (CBI).

This document contains highly sensitive information. Due to confidentiality, materials with such information are not available in SDMS. You may contact the EPA Superfund Records Manager if you wish to view this document.

Specify Type of Document(s) / Comments:

Unscannable Material:

Oversized ____ or ____ Format.

Due to certain scanning equipment capability limitations, the document page(s) is not available in SDMS. The original document is available for viewing at the Superfund Records center.

Specify Type of Document(s) / Comments:

Document is available at the EPA Region 5 Records Center.

Specify Type of Document(s) / Comments:

Envirochem

WPCLMB

WJ INFOMASTER 4-0342415334-001 11/29/84
 ICS IPMBNGZ CSP
 3128866335 DGM TDBN CHICAGO IL 286 11-29 0405P EST
 TWX 9102215191 WPCLMB
 EMERGENCY RESPONSE
 4224 EPA EMER

[NOVEMBER 29, 1984

POLRET 13 IMMEDIATE REMOVAL-ENVIRO CHEM SITE ZIONSVILLE INDIANA
 A POLLUTION-ACTION FOR CLEANING/DISPOSAL OF TANKS AND COOLING WATER
 POND.

B. ACTION-ALL OF THE 63 TANKS HAVE BEEN CLEANED AND STAGED AND ARE TO BE
 REMOVED FROM THE SITE BY THE OWNER OF THE TANKS. 881,000 GALLONS OF
 CONTAMINATED SURFACE WATER HAVE BEEN SHIPPED OFF-SITE. 91,400 OF WASTE
 HAVE BEEN REMOVED FROM THE TANKS AND DISPOSED OFF-SITE. 1,500 CUBIC
 YARDS OF SLUDGE HAVE BEEN EXCAVATED FROM THE COOLING POND AND STORED ON
 THE AREA JUST SOUTH OF THE POND. ABOUT 1,000 CUBIC YARDS OF THE
 EXCAVATED SLUDGE HAS BEEN MIXED WITH THE TANK WASTE AND DISPOSED
 OFF-SITE. 800 CUBIC YARDS OF SITE SOIL FROM BENEATH THE TANKS AND AROUND
 THE BUILDING HAS BEEN EXCAVATED AND STORED JUST SOUTH OF THE POND. A 1-2
 FOOT CLAY CAP HAS BEEN PLACED BY THE LAND OWNER UNDER THE DIRECTION OF
 THE OSC.

C. PROBLEMS-7 LOADS OF THE PCB SLUDGE BOUND FOR THE ESI DISPOSAL

ESI FACILITY. NO PCB'S WERE FOUND IN THE LEAKAGE, BUT SUBSTANTIAL
 ADDITIONAL CHARGES TO DRAIN AND SOLIFY THE LIQUIDS AND TO DECONTAMINATE
 THE TRUCKS, WERE INCURRED. THE PROBLEM WAS APPARENTLY DUE TO INADEQUATE
 SOLIDIFICATION AND IMPROPER PLACEMENT OF THE LINERS IN THE TRUCKS.

D. FUTURE ACTION-THE WORK IS ALMOST 100 PERCENT COMPLETED. ONE JOB
 TRAILER REMAINS ON SITE IN ORDER FOR THE OSC TO MONITOR THE SITE CAPPING
 OPERATION. ONCE THE CAPPING IS COMPLETE SOME FENCE REPAIR WILL PROBABLY

BE REQUIRED, COSTING LESS THAN \$5,000.
 E* EXPENDITURES-APPROXIMATELY \$1,025,000 HAVE BEEN EXPENDED: \$11,000
 REMAIN IN THE PROJECT CEILING. THE ADDITIONAL CHARGES AT THE ESI
 FACILITY MAY CAUSE THE CEILING TO BE EXCEEDED.

JUSTINE BOLDEN

1611 EST

WJE

THE OSC.

C. PROBLEMS-7 LOADS OF THE PCB SLUDGE BOUND FOR THE ESI DISPOSAL
 FACILITY IN GRANDVIEW IDAHO WERE FOUND TO BE LEAKING AS THEY ENTERED THE
 ESI FACILITY. NO PCB'S WERE FOUND IN THE LEAKAGE, BUT SUBSTANTIAL
 ADDITIONAL CHARGES TO DRAIN AND SOLIFY THE LIQUIDS AND TO DECONTAMINATE
 THE TRUCKS, WERE INCURRED. THE PROBLEM WAS APPARENTLY DUE TO INADEQUATE
 SOLIDIFICATION AND IMPROPER PLACEMENT OF THE LINERS IN THE TRUCKS.

D. FUTURE ACTION-THE WORK IS ALMOST 100 PERCENT COMPLETED. ONE JOB
 TRAILER REMAINS ON SITE IN ORDER FOR THE OSC TO MONITOR THE SITE CAPPING
 OPERATION. ONCE THE CAPPING IS COMPLETE SOME FENCE REPAIR WILL PROBABLY
 BE REQUIRED, COSTING LESS THAN \$5,000.

E* EXPENDITURES-APPROXIMATELY \$1,025,000 HAVE BEEN EXPENDED: \$11,000
 REMAIN IN THE PROJECT CEILING. THE ADDITIONAL CHARGES AT THE ESI
 FACILITY MAY CAUSE THE CEILING TO BE EXCEEDED.

JUSTINE BOLDEN

1611 EST